

R2 DON'T overcut hole and damage flange.

