

R7

DON'T cut beyond inside edge of bearing.

